




**PART# 8985, 8989**  
Part# 8985 TH700-R4 Braided TV Cable  
Part# 8989 TH350 Braided TV Cable

## TH700-R4/TH350 THROTTLE VALVE (TV) CABLE WARNING: SEVERE DAMAGE MAY OCCUR IF TV CABLE IS NOT ADJUSTED CORRECTLY

**IMPORTANT:** Follow diagram below. Be sure the TV cable movement feels free and is consistent with the measurements stated. It is **VERY** important that the cable operates within these parameters. Damage may occur if not adjusted correctly.



**NOTE:** CHECK CABLE PERIODICALLY AND REPLACE IF THERE ARE ANY SIGNS OF WEAR OR KINKING OF THE HOUSING OR WIRE. AS THIS COULD CAUSE THE CABLE TO STICK OR FAIL CAUSING INJURY OR DAMAGE.